CLASSIFICAT	TION SECRET/CONTROL _ U.S. OFFICIALS ONLY	
COUNTRY East Germany  TOPIC Forst-Jocksdorf Airs	REPORT	25X1
		618464
EVALUATION	PLACE OBTAINED	
DATE OF CONTENT.		25X1
DATE OBTAINED	DATE PREPARED 26 March 195	HALL
REFERENCES		- Comment with the Comment of the Co
PAGES PENCLOSURES	(NO. & TYPE)	resident and the second of
REMARKS		
This is	UNEVALUATED Information	·
	A THE PARTY OF THE	

25X1

1.

construction material shipments arriving at Forst-Jocksdorf

airfield:

Date	Number of Railroad Cars	Cargo	From	i de la composição de l
l January	2	steel containers	Halle	
	30	first quality chippings	Gollnow and Schwarzkollm	
2 January	14	<b>19</b>	Seelings taedt	
4 January	10	cement	Nienburg	
	15	chippings	Hohenbocka, Gollnow and Witticherau	l
5 January	6	cement	Nienburg	
	3	greenstone first quality chippings	Riesa	
6 January	7	cement	Nienburg	
, s	6	first quality chippings	Wildschuetz and Seeling staedt	ğ-
7 January	5	cement	Nienburg	
	6	first quality chippings	Sealingstaedt	
	2	steel containers	Halle	
20 January	6	cement	Nienburg	

CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY

SECRET/CONTROL - U.S. OFFICIALS ONLY					
				25X1	
		<b>2</b> ···			
20 January	2	steel containers	Halle		
	9	first quality chippings	Wittichenau		
21 January	4	cement	Nienburg		
•	6	chippings	Schwarzkollm		
22 January	7	15	Wittichenau		
15 February	2	lime	Charlottenhof		
	3	steel and profile iron	Dresden-Altstadt		
	4	sawn timber	Weisswasser		

During February, no construction work was being done at the field. On 19 February, the Gross-Schacksdorf-Preschen road was still open for regular traffic. Numerous pegs were put into the ground in the estern extension of the runway beyond the road. These pegs were arranged in straight lines and in curves. No excavation work was seen east of the road. The western end of the runway which extended to as far ash Jocks-dorf-Gosda road was concreted.

| cleaning had been done on the clean of the runway. Steel trestles were identified at the northern edge of the runway and east of the conrete mixing installation, the latter located approximately at the point where the former Gross-Schacksdorf-Gosda road crossed the runway.

Comment. No progress in improvement work at Jocksdorf airfield has apparently been made since the end of 1953.

SECRET/CONTROL - U.S. OFFICIALS ONLY